


# Exposure-Mat MINI

The No Battery Exposure Meter




expomat.tripod.com

© 2003 INFORMATIQUES

## Assembly Instructions

- 1 Print on 140 gsm card stock.
- 2 Lightly score fold lines A & B in 1.
- 3 Cut out centre rectangle from 1 using a craft knife and ruler.
- 4 Cut out 1 using craft knife and ruler.
- 5 Carefully fold 1 at A and B.
- 6 Cut out 2 using craft knife and ruler.
- 7 Assemble by sliding 2 into 1, check fit and adjust by trimming bottom edge of 2 if necessary.
- 8 Springily apply glue to marked section of 1, fold and leave to dry.
- 9 When dry slide 2 into 1 and follow use instructions.



## Use Instructions

- 1 Align film speed with Exposure Value at top of window.
- 2 Read possible Aperture / Shutter Speed combinations at bottom of window.
- 3 For more information -  
 "The Ultimate Exposure Meter"  
[www.fredparker.com](http://www.fredparker.com)  
 "Who needs A Light Meter Anyway?"  
[http://www.pcisys.net/~rlnpjs/minolta/ev\\_lv\\_asa.html](http://www.pcisys.net/~rlnpjs/minolta/ev_lv_asa.html)  
 "Freebie Pocket Exposure Calculator"  
[rick\\_oleson.tripod.com](http://rick_oleson.tripod.com)  
 and watch our site for updates  
[expomat.tripod.com](http://expomat.tripod.com)